




CONTACTEUR	POS	FONCTION
S1 a b	1	ARRET - C.C. de M3
	2	MARCHE
S2	1	115V
	2	127
	3	160 50HZ - 400HZ
	4	220
	5	230v
S3 a...f	1	AC
	2	- DC
	3	+
	4	↑
	5	OHMS
S4 a...d	1	ZERO DC
	2	100mV=, OHMS
	3	300mV=, OHMS x 10
	4	1V, OHMS x 100
	5	3V, KΩ
	6	10V, KΩ x 10
	7	30V, KΩ x 100
	8	100V, MΩ
	9	300V, MΩ x 10
	10	1000V, DC
	11	ZERO DC
S5	1	X1
	2	X0,5
S6 a...c	1	ELECTROMETRE 0 à 10V
	2	NORMAL R = 100M
	3	CHARGE - ZERO = DC
	4	MEMOIRE

